SUMMARY OF VERDE RIVER CHANNEL CONDITIONS NOTED DURING THE MARCH 1911 GLO SURVEY OF T4N, R7E^a

DATE	SURVEY SECTION(S)	PAGE NUMBER IN FIELD NOTES	MAIN CHANNEL			SHALLOW CHANNEL		
			Width		Depth	Width		Depth
			(Chains)	(Feet)	(Feet)	(Chains)	(Feet)	(Feet)
3/1/1911	30 and 31	3	-					1 to 2
	31	5	14	924				
3/2/1911		7	34 (?)	2,244 (?)	3			
		8	6	396	4			
3/3/1911	30	13	19	1,254	1 to 2			
3/8/1911	20 and 29	41	4	264				1 to 2
	29	45	7.1	469	3	1		1 to 2
	17 and 20	49	6.4	422		7.4	488	1 to 2
	20	51	6.6	436		1 to		1 to 2
3/9/1911		52	"At this point, the river channel is too wide and swift to permit direct measurement."					
		53				3	198	1 to 2
3/10/1911		55			2 to 3			
	8 and 17	59	9	594		3	198	1 to 2
						5.9	389	3
3/11/1911	17	61	17.8	1,175				
		62	12.2	805				
		64	16.5	1,089				
3/13/1911	8	69	15.6	1,030	3			
		71	11.4	752		3.7	244	1

Note:

Plateau Resources LLC January 2015

^a From Arizona Survey Book 2397 by Robert A. Farmer, approved March 29, 1913.